

FEDERAL AVIATION ADMINISTRATION (FAA) APPROVED MODEL LIST (AML)

Original Issue Date March 7, 2018
Revision H December 17, 2025

FOR DYNON AVIONICS STC SA02594SE

INSTALLATION OF THE SKYVIEW HDX INSTRUMENTATION AND AUTOPILOT SYSTEM

ITEM	AIRCRAFT / ROTORCRAFT MAKE	AIRCRAFT / ROTORCRAFT MODEL	ORIGINAL TC NUMBER	CERTIFICATION BASIS FOR ALTERATION	FAA APPROVED DOCUMENTS Number and Revision (or later FAA approved revision)	NOTES AND LIMITATIONS	AML REV DATE
1	Aermacchi S.p.A (Aermacchi S.p.A) [Siai Marchetti]	F.260, F.260B, F.260C, F.260D, F.260E, F.260F	A10EU	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
2	Aermacchi S.p.A (Aermacchi S.p.A) [Siai Marchetti]	S.205-18/F, S.205-18/R, S.205-20/F, S.205-20/R, S.205- 22/R, S.208, S.208A	A9EU	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
3	Aero Commander (Dynac Aerospace Corp) [Voltaire]	10, 10A, 100, 100A, 100-180	1A21	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
4	Aerotek II (Callair)	B-1, B-1A	A7WE	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
5	Aircraft Parts & Development Corp. (Callair)	A, A-2, A-3,A-4, A-5, A-5T, A-6, A-7, A7T, A-9, A-9B	A-758	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
6	Alexandria Aircraft (Alexandria Aircraft LLC) [Bellanca]	17-30A, 17-31A, 17-31ATC	A18CE	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	

FEDERAL AVIATION ADMINISTRATION (FAA) APPROVED MODEL LIST (AML)

Original Issue Date March 7, 2018
Revision H December 17, 2025

FOR DYNON AVIONICS STC SA02594SE

INSTALLATION OF THE SKYVIEW HDX INSTRUMENTATION AND AUTOPILOT SYSTEM

ITEM	AIRCRAFT / ROTORCRAFT MAKE	AIRCRAFT / ROTORCRAFT MODEL	ORIGINAL TC NUMBER	CERTIFICATION BASIS FOR ALTERATION	FAA APPROVED DOCUMENTS Number and Revision (or later FAA approved revision)	NOTES AND LIMITATIONS	AML REV DATE
7	Alexandria Aircraft (Alexandria Aircraft, LLC) [Bellanca]	14-19, 14-19-2, 14-19-3, 14-19-3A, 17-30, 17-31, 17-31TC	1A3	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
8	American Champion (American Champion Aircraft Corporation)	7ECA, 7GCAA, 7GCBC, 7KCAB	A-759	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
9	American Champion (American Champion Aircraft Corporation)	8KCAB, 8GCBC	A21CE	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
10	AUGUSTAIR (Morrisey, Varga)	2150, 2150A, 2180	4A19	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
11	Aviat Aircraft, Inc. (Aviat Aircraft, Inc.) [Sky International]	A-1, A-1A, A-1B, A-1C-180, A-1C-200	A22NM	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
12	Aviat Aircraft, Inc. (Aviat Aircraft, Inc.) [Sky International]	S-1S, S-1T, S-2, S-2A, S-2S, S-2B, S-2C	A8SO	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	

**FEDERAL AVIATION ADMINISTRATION (FAA) APPROVED MODEL LIST (AML)
FOR DYNON AVIONICS STC SA02594SE**

Original Issue Date March 7, 2018
Revision H December 17, 2025

INSTALLATION OF THE SKYVIEW HDX INSTRUMENTATION AND AUTOPILOT SYSTEM

ITEM	AIRCRAFT / ROTORCRAFT MAKE	AIRCRAFT / ROTORCRAFT MODEL	ORIGINAL TC NUMBER	CERTIFICATION BASIS FOR ALTERATION	FAA APPROVED DOCUMENTS Number and Revision (or later FAA approved revision)	NOTES AND LIMITATIONS	AML REV DATE
13	Bellanca (Bellanca Aircraft Corporation)	14-13-2, 14-13-3W, 14-13-3, 14-13	A-773	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
14	Boeing (The Boeing Company) [Rockwell International]	BC-1A, AT-6 (SNJ-2), AT-6A (SNJ-3), AT-6B, AT-6C (SNJ-4), AT-6D (SNJ-5), AT-6F (SNJ-6), SNJ-7, T-6G	A-2-575	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
15	Cessna (Reims Aviation Industries)	FR172E FR172F, FR172G, FR172H, FR172J, FR172K	A18EU	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
16	Cessna (Reims Aviation Industries)	F172D, F172E, F172F, F172G, F172H, F172K, F172L, F172M, F172N, F172P, FP172D	A4EU	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
17	Cessna (Reims Aviation Industries)	F177RG	A26EU	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
18	Cessna (Reims Aviation Industries)	F182P, F182Q, FR182	A42EU	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	

**FEDERAL AVIATION ADMINISTRATION (FAA) APPROVED MODEL LIST (AML)
FOR DYNON AVIONICS STC SA02594SE**

Original Issue Date March 7, 2018
Revision H December 17, 2025

INSTALLATION OF THE SKYVIEW HDX INSTRUMENTATION AND AUTOPILOT SYSTEM

ITEM	AIRCRAFT / ROTORCRAFT MAKE	AIRCRAFT / ROTORCRAFT MODEL	ORIGINAL TC NUMBER	CERTIFICATION BASIS FOR ALTERATION	FAA APPROVED DOCUMENTS Number and Revision (or later FAA approved revision)	NOTES AND LIMITATIONS	AML REV DATE
19	Commander (Commander Aircraft Corporation) [CPAC, Inc.]	112, 112TC, 112B, 112TCA, 114, 114A, 114B, 114TC	A12SO	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
20	Cub Crafters (Cub Crafters Inc.)	CC19-180	A00053SE	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
21	DeHavilland Support Limited	Beagle B.121 Series 1, Beagle B.121 Series 2, Beagle B.121 Series 3	A22EU	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
22	Discovery	XL-2	A00008DE	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
23	EADS-PZL "Warszawa-Okecie" (EADS-PZL "Warszawa-Okecie" S.A.)	PZL-104 WILGA 80, PZL-104M WILGA 2000, PZL-104MA WILGA 2000	A55EU	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
24	EADS-PZL "Warszawa-Okecie" (EADS-PZL "Warszawa-Okecie" S.A.)	PZL-KOLIBER 150A, PZL-KOLIBER 160A	A69EU	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	

**FEDERAL AVIATION ADMINISTRATION (FAA) APPROVED MODEL LIST (AML)
FOR DYNON AVIONICS STC SA02594SE**

Original Issue Date March 7, 2018
Revision H December 17, 2025

INSTALLATION OF THE SKYVIEW HDX INSTRUMENTATION AND AUTOPILOT SYSTEM

ITEM	AIRCRAFT / ROTORCRAFT MAKE	AIRCRAFT / ROTORCRAFT MODEL	ORIGINAL TC NUMBER	CERTIFICATION BASIS FOR ALTERATION	FAA APPROVED DOCUMENTS Number and Revision (or later FAA approved revision)	NOTES AND LIMITATIONS	AML REV DATE
25	Found Brothers (Found Brothers Aviation Limited)	FBA Centennial "100"	A13EA	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
26	FS2003 Corp. (FS 2003 Corporation) [The New Piper Aircraft, Inc.]	PA-12, PA-12S	A-780	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
27	Fuji (Fuji Heavy Industries, Ltd)	FA-200-160, FA-200-180, FA-200-180AO	A4PC	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
28	Helio (Helio Aircraft, LLC)	H-250,H-295 (USAF U-10D), HT-295, H-391 (USAF YL- 24), H-391B, H-395 (USAF L-28A or U-10B), H-395A, H-700, H-800	1A8	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
29	Howard Aircraft Foundation	DGA-15P (Army UC-70; Navy GH-1, GH-2, GH-3, NH-1), DGA-15J (Army UC-70B) DGA-15W	A-717	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
30	Howard Aircraft Foundation	DGA-11	TC 672	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	

FEDERAL AVIATION ADMINISTRATION (FAA) APPROVED MODEL LIST (AML)

Original Issue Date March 7, 2018
Revision H December 17, 2025

FOR DYNON AVIONICS STC SA02594SE

INSTALLATION OF THE SKYVIEW HDX INSTRUMENTATION AND AUTOPILOT SYSTEM

ITEM	AIRCRAFT / ROTORCRAFT MAKE	AIRCRAFT / ROTORCRAFT MODEL	ORIGINAL TC NUMBER	CERTIFICATION BASIS FOR ALTERATION	FAA APPROVED DOCUMENTS Number and Revision (or later FAA approved revision)	NOTES AND LIMITATIONS	AML REV DATE
31	Howard Aircraft Foundation	DGA-9 (Army UC-70D) DGA-12 (Army UC-70A)	TC 645	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
32	Howard Aircraft Foundation	DGA-18 DGA-18K	TC 739	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
33	Howard Aircraft Foundation	DGA-8 (Army UC-70C)	TC 612	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
34	Interceptor (Interceptor Aircraft Inc) [Prop-Jets, Inc.; Meyers]	200, 200A, 200B, 200C, 200D, 400	3A18	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
35	JGS (JGS Properties, LLC) [Quartz Mountain Aerospace; Luscombe Aircraft]	11E	A-804	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
36	Luscombe (Good Earthkeeping Organization Inc)	8A, 8B, 8C, 8D, 8E, 8F, 8, T-8F	A-694	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	

**FEDERAL AVIATION ADMINISTRATION (FAA) APPROVED MODEL LIST (AML)
FOR DYNON AVIONICS STC SA02594SE**

Original Issue Date March 7, 2018
Revision H December 17, 2025

INSTALLATION OF THE SKYVIEW HDX INSTRUMENTATION AND AUTOPILOT SYSTEM

ITEM	AIRCRAFT / ROTORCRAFT MAKE	AIRCRAFT / ROTORCRAFT MODEL	ORIGINAL TC NUMBER	CERTIFICATION BASIS FOR ALTERATION	FAA APPROVED DOCUMENTS Number and Revision (or later FAA approved revision)	NOTES AND LIMITATIONS	AML REV DATE
37	Maule (Maule Aerospace Technology, Inc)	Bee Dee M-4, M-4, M-4C, M-4S, M4T, M-4-180C, M-4-180S, M-4-180T, M-4-180V, M-4-210, M-4-210C, M-4-210S, M-4-210T, M-4-220, M-4-220C, M4-220S, M-4-220T, M-5-180C, M-5-200, M-5-210C, M5-210TC, M-5-220C, M-5-235C, M-6-180, M-6-235, M-7-235, MX-7-235, MX-7-180, MX-7-420, MXT-7-180, MT-7-235, MX-7-160, MXT-7-160, MX-7-180A, MXT7-180A, MX-7-180B, M-7-235B, M-7-235A, M-7-235C, MX-7-180C, M-7-260, MT-7-260, M-7- 260C, M-7-420AC, MX-7-160C, MX-7-180AC, M7-420A, MT-7-420, M-8-235	3A23	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	

**FEDERAL AVIATION ADMINISTRATION (FAA) APPROVED MODEL LIST (AML)
FOR DYNON AVIONICS STC SA02594SE**

Original Issue Date March 7, 2018
Revision H December 17, 2025

INSTALLATION OF THE SKYVIEW HDX INSTRUMENTATION AND AUTOPILOT SYSTEM

ITEM	AIRCRAFT / ROTORCRAFT MAKE	AIRCRAFT / ROTORCRAFT MODEL	ORIGINAL TC NUMBER	CERTIFICATION BASIS FOR ALTERATION	FAA APPROVED DOCUMENTS Number and Revision (or later FAA approved revision)	NOTES AND LIMITATIONS	AML REV DATE
38	Monocoupe Corporation	90, 90A, 90AF, 90AF-100, 90AL-115	A-306	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
39	Mooney (Mooney Aircraft Corporation)	M22	A6SW	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
40	Mooney (Mooney International Corporation) [Mooney Aviation Company, Inc.; Mooney Airplane Co.; Mooney Aircraft Corporation; Aerostar Aircraft Corp]	M20, M20A, M20B, M20G, M20L, M20M, M20R, M20S	2A3	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	12/17/2025
41	Nardi (Nardi S.A.) [Siai Marchetti]	FN-333	7A5	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
42	Navion (Sierra Hotel Aero, Inc.)	Navion (L-17A), Navion A (L-17B, L-17C), Navion B, Navion D, Navion E, Navion F, Navion G, Navion H	A-782	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
43	Pacific Aerospace Limited. (Pacific Aerospace Ltd.) [Found Aircraft Canada, Inc]	FBA-2C, FBA-2C1 (Bush Hawk), FBA-2C2 (Bush Hawk XP)	A7EA	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	

FEDERAL AVIATION ADMINISTRATION (FAA) APPROVED MODEL LIST (AML)

Original Issue Date March 7, 2018
Revision H December 17, 2025

FOR DYNON AVIONICS STC SA02594SE

INSTALLATION OF THE SKYVIEW HDX INSTRUMENTATION AND AUTOPILOT SYSTEM

ITEM	AIRCRAFT / ROTORCRAFT MAKE	AIRCRAFT / ROTORCRAFT MODEL	ORIGINAL TC NUMBER	CERTIFICATION BASIS FOR ALTERATION	FAA APPROVED DOCUMENTS Number and Revision (or later FAA approved revision)	NOTES AND LIMITATIONS	AML REV DATE
44	Piper Aircraft, Inc. (Piper Aircraft, Inc.)	PA-16, PA-16S	1A1	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
45	Piper Aircraft, Inc. (Piper Aircraft, Inc.)	PA-18, PA-18 "105", PA-18 "125" (Army L-21A), PA-18S, PA-18S "105", PA-18S "125", PA-18AS "125", PA-18 "135" (Army L-21B), PA-18A, PA-18A "135", PA-18S "135", PA-18AS "135", PA-18 "150", PA-18A "150", PA-18S "150", PA-18AS "150", PA-19 (Army L-18C), PA-19S	1A2	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
46	Piper Aircraft, Inc. (Piper Aircraft, Inc.)	PA-20, PA-20S, PA-20 "115", PA-20S "115", PA-20 "135", PA-20S "135"	1A4	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
47	Piper Aircraft, Inc. (Piper Aircraft, Inc.)	PA-22, PA-22-108, PA-22-135, PA-22S-135, PA-22-150, PA-22S-150, PA-22-160, PA-22S-160	1A6	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	

FEDERAL AVIATION ADMINISTRATION (FAA) APPROVED MODEL LIST (AML)

Original Issue Date March 7, 2018
Revision H December 17, 2025

FOR DYNON AVIONICS STC SA02594SE

INSTALLATION OF THE SKYVIEW HDX INSTRUMENTATION AND AUTOPILOT SYSTEM

ITEM	AIRCRAFT / ROTORCRAFT MAKE	AIRCRAFT / ROTORCRAFT MODEL	ORIGINAL TC NUMBER	CERTIFICATION BASIS FOR ALTERATION	FAA APPROVED DOCUMENTS Number and Revision (or later FAA approved revision)	NOTES AND LIMITATIONS	AML REV DATE
48	Piper Aircraft, Inc. (Piper Aircraft, Inc.)	PA-24, PA-24-250, PA-24-260, PA-24-400	1A15	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
49	Piper Aircraft, Inc. (Piper Aircraft, Inc.)	PA-28-140, PA-28-150, PA-28-151, PA-28-160, PA-28-161, PA-28-180, PA-28-235, PA-28S-160, PA-28R-180, PA-28S-180, PA-28-181, PA-28R-200, PA-28R-201, PA-28R-201T, PA-28RT-201, PA-28RT-201T, PA-28-201T, PA-28-236	2A13	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
50	Piper Aircraft, Inc. (Piper Aircraft, Inc.)	PA-34-200	A7SO	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
51	Piper Aircraft, Inc. (Piper Aircraft, Inc.)	PA-34-200T PA-34-220T	A7SO	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021 Autopilot Servo Installation & Maintenance Manual: 103741-000 Revision F dated 4/21/2022	Autopilot Installation Optional Autotrim Installation Optional	

FEDERAL AVIATION ADMINISTRATION (FAA) APPROVED MODEL LIST (AML)

Original Issue Date March 7, 2018
Revision H December 17, 2025

FOR DYNON AVIONICS STC SA02594SE

INSTALLATION OF THE SKYVIEW HDX INSTRUMENTATION AND AUTOPILOT SYSTEM

ITEM	AIRCRAFT / ROTORCRAFT MAKE	AIRCRAFT / ROTORCRAFT MODEL	ORIGINAL TC NUMBER	CERTIFICATION BASIS FOR ALTERATION	FAA APPROVED DOCUMENTS Number and Revision (or later FAA approved revision)	NOTES AND LIMITATIONS	AML REV DATE
52	Piper Aircraft, Inc. (Piper Aircraft, Inc.)	PA-38-112	A18SO	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
53	Piper Aircraft, Inc. (Piper Aircraft, Inc.)	PA-32-260, PA-32-300, PA-32S-300, PA-32R-300, PA- 32RT-300, PA-32RT-300T, PA-32R-301(SP), PA-32R- 301(HP), PA-32R-301T, PA-32-301, PA-32-301T, PA-32- 301FT, PA-32-301XTC	A3SO	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
54	Polskie Zakłady Lotnicze Spolka zo.o (Polskie Zakłady Lotnicze Spolka zo.o) [PZL MIELEC]	PZL M26 01	A44CE	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
55	Regal Air, Inc. (Cessna)	(USAF 0-1A) 305A, (USAF 0-1E) 305C, (USAF 0-1G) 305D 305F	5A5	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
56	Regal Air, Inc. (Cessna)	(Military 305B TO-1D, O-1D, O-1F) 305E	3A14	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	

FEDERAL AVIATION ADMINISTRATION (FAA) APPROVED MODEL LIST (AML)

Original Issue Date March 7, 2018
Revision H December 17, 2025

FOR DYNON AVIONICS STC SA02594SE

INSTALLATION OF THE SKYVIEW HDX INSTRUMENTATION AND AUTOPILOT SYSTEM

ITEM	AIRCRAFT / ROTORCRAFT MAKE	AIRCRAFT / ROTORCRAFT MODEL	ORIGINAL TC NUMBER	CERTIFICATION BASIS FOR ALTERATION	FAA APPROVED DOCUMENTS Number and Revision (or later FAA approved revision)	NOTES AND LIMITATIONS	AML REV DATE
57	Revo, Inc. (Revo, Incorporated) [Lake]	Colonial C-1 Colonial C-2 Lake LA-4 Lake LA-4A Lake LA-4P Lake LA-4-200 Lake Model 250	1A13	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
58	Socata Morane Saulnier Rallye (SOCATA) [SOCATA - Groupe Aerospatiale]	Rallye 100S, Rallye 150ST, Rallye 150T, Rallye 235E, Rallye 235C, MS 880B, MS 885, MS 894A, MS 893A, MS 892A-150, MS 892E-150, MS 893E, MS 894E	7A14	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
59	Socata Morane Saulnier Rallye (SOCATA) [SOCATA - Groupe Aerospatiale]	TB 9, TB 10, TB 20, TB 21, TB 200	A51EU	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
60	Spartan Aircraft Company	Spartan 7W	TC 628	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
61	STOL (Sky Enterprises, Inc.) [Republic Sea-Bee]	RC-3	A-769	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	

FEDERAL AVIATION ADMINISTRATION (FAA) APPROVED MODEL LIST (AML)

Original Issue Date March 7, 2018
Revision H December 17, 2025

FOR DYNON AVIONICS STC SA02594SE

INSTALLATION OF THE SKYVIEW HDX INSTRUMENTATION AND AUTOPILOT SYSTEM

ITEM	AIRCRAFT / ROTORCRAFT MAKE	AIRCRAFT / ROTORCRAFT MODEL	ORIGINAL TC NUMBER	CERTIFICATION BASIS FOR ALTERATION	FAA APPROVED DOCUMENTS Number and Revision (or later FAA approved revision)	NOTES AND LIMITATIONS	AML REV DATE
62	Swift (Swift Museum Foundation Inc.) [Globe Aircraft Company]	GC-1A, GC-1B	A-766	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
63	Symphony Aircraft Industries Inc. (Symphony Aircraft Industries Inc.) [OMF]	OMF-100-160, SA 160	A46CE	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
64	Textron Aviation (Textron Aviation Inc.) [Beechcraft]	19A, B19, M19A, 23, A23, A23A, A23-19, A23-24, B23, C23, A24, A24R, B24R, C24R	A1CE	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
65	Textron Aviation (Textron Aviation Inc.) [Beechcraft]	S35, V35, V35A, V35B	3A15	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021 Autopilot Servo Installation & Maintenance Manual: 103662-000 Revision B dated 5/8/2019	Autopilot Installation Optional Autotrim Installation Optional	
66	Textron Aviation (Textron Aviation Inc.) [Beechcraft]	35-33, 35-A33, 35-B33, 35-C33, 35-C33A, E33, E33A, E33C, F33, F33A, F33C, G33, H35, J35, K35, M35, N35	3A15	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	

FEDERAL AVIATION ADMINISTRATION (FAA) APPROVED MODEL LIST (AML)

Original Issue Date March 7, 2018
Revision H December 17, 2025

FOR DYNON AVIONICS STC SA02594SE

INSTALLATION OF THE SKYVIEW HDX INSTRUMENTATION AND AUTOPILOT SYSTEM

ITEM	AIRCRAFT / ROTORCRAFT MAKE	AIRCRAFT / ROTORCRAFT MODEL	ORIGINAL TC NUMBER	CERTIFICATION BASIS FOR ALTERATION	FAA APPROVED DOCUMENTS Number and Revision (or later FAA approved revision)	NOTES AND LIMITATIONS	AML REV DATE
67	Textron Aviation (Textron Aviation Inc.) [Beechcraft]	35, A35, B35, C35, D35, E35, F35, G35	A-777	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
68	Textron Aviation (Textron Aviation Inc.) [Beechcraft]	36, A36, A36TC, B36TC	3A15	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021 Autopilot Servo Installation & Maintenance Manual: 103736-000 Revision F dated 4/14/2023	Autopilot Installation Optional Autotrim Installation Optional	1/5/2022
69	Textron Aviation (Textron Aviation Inc.) [Beechcraft]	58, 58A	3A16	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021 Autopilot Servo Installation & Maintenance Manual: 104257-000 Revision E dated 12/6/2023	Autopilot Installation Optional Autotrim Installation Optional	12/7/2023
70	Textron Aviation (Textron Aviation Inc.) [Beechcraft]	45 (YT-34), A45 (T-34A, B-45), D45 (T-34B)	5A3	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
71	Textron Aviation (Textron Aviation Inc.) [Beechcraft]	77	A30CE	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	

**FEDERAL AVIATION ADMINISTRATION (FAA) APPROVED MODEL LIST (AML)
FOR DYNON AVIONICS STC SA02594SE**

Original Issue Date March 7, 2018
Revision H December 17, 2025

INSTALLATION OF THE SKYVIEW HDX INSTRUMENTATION AND AUTOPILOT SYSTEM

ITEM	AIRCRAFT / ROTORCRAFT MAKE	AIRCRAFT / ROTORCRAFT MODEL	ORIGINAL TC NUMBER	CERTIFICATION BASIS FOR ALTERATION	FAA APPROVED DOCUMENTS Number and Revision (or later FAA approved revision)	NOTES AND LIMITATIONS	AML REV DATE
72	Textron Aviation (Textron Aviation Inc.) [Beechcraft]	D17S (Army UC-43, UC-43B, Navy GB-1, GB-2), SD17S	A-649	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
73	Textron Aviation (Textron Aviation Inc.) [Beechcraft]	G17S	TC 779	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
74	Textron Aviation Inc. (Textron Aviation Inc.) [Cessna Aircraft Company]	140A	5A2	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
75	Textron Aviation Inc. (Textron Aviation Inc.) [Cessna Aircraft Company]	120, 140	A-768	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
76	Textron Aviation Inc. (Textron Aviation Inc.) [Cessna Aircraft Company]	150, 150A, 150B, 150C, 150D, 150E, 150F, 150G, 150H, 150J, 150K, A150K, 150L, A150L, 150M, A150M, 152, A152	3A19	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
77	Textron Aviation Inc. (Textron Aviation Inc.) [Cessna Aircraft Company]	170, 170A, 170B	A-799	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	

**FEDERAL AVIATION ADMINISTRATION (FAA) APPROVED MODEL LIST (AML)
FOR DYNON AVIONICS STC SA02594SE**

Original Issue Date March 7, 2018
Revision H December 17, 2025

INSTALLATION OF THE SKYVIEW HDX INSTRUMENTATION AND AUTOPILOT SYSTEM

ITEM	AIRCRAFT / ROTORCRAFT MAKE	AIRCRAFT / ROTORCRAFT MODEL	ORIGINAL TC NUMBER	CERTIFICATION BASIS FOR ALTERATION	FAA APPROVED DOCUMENTS Number and Revision (or later FAA approved revision)	NOTES AND LIMITATIONS	AML REV DATE
78	Textron Aviation Inc. (Textron Aviation Inc.) [Cessna Aircraft Company]	172F (USAF T-41A), 172G, 172H (USAF T-41A), 172I, 172K, 172L, 172M, 172N, 172P, 172Q, 172R, 172S	3A12	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021 Autopilot Servo Installation & Maintenance Manual: 103526-000 Revision E dated 4/21/2022	Autopilot Installation Optional	
79	Textron Aviation Inc. (Textron Aviation Inc.) [Cessna Aircraft Company]	172, 172A, 172B, 172C, 172D, 172E	3A12	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
80	Textron Aviation Inc. (Textron Aviation Inc.) [Cessna Aircraft Company]	175, 175A, 175B, 175C, P172D, R172E (USAF T-41B), (USAF T-41C or D), R172F (USAF T-41D), R172G (USAF T-41C or D), R172H (USAF T-41D), R172J, 172RG, R172K	3A17	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
81	Textron Aviation Inc. (Textron Aviation Inc.) [Cessna Aircraft Company]	177, 177A, 177B	A13CE	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
82	Textron Aviation Inc. (Textron Aviation Inc.) [Cessna Aircraft Company]	177RG	A20CE	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	

FEDERAL AVIATION ADMINISTRATION (FAA) APPROVED MODEL LIST (AML)

Original Issue Date March 7, 2018
Revision H December 17, 2025

FOR DYNON AVIONICS STC SA02594SE

INSTALLATION OF THE SKYVIEW HDX INSTRUMENTATION AND AUTOPILOT SYSTEM

ITEM	AIRCRAFT / ROTORCRAFT MAKE	AIRCRAFT / ROTORCRAFT MODEL	ORIGINAL TC NUMBER	CERTIFICATION BASIS FOR ALTERATION	FAA APPROVED DOCUMENTS Number and Revision (or later FAA approved revision)	NOTES AND LIMITATIONS	AML REV DATE
83	Textron Aviation Inc. (Textron Aviation Inc.) [Cessna Aircraft Company]	180, 180A, 180B, 180C, 180D, 180E, 180F, 180G, 180H, 180J, 180K	5A6	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
84	Textron Aviation Inc. (Textron Aviation Inc.) [Cessna Aircraft Company]	182, 182A, 182B, 182C, 182D	3A13	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
85	Textron Aviation Inc. (Textron Aviation Inc.) [Cessna Aircraft Company]	182E, 182F, 182G, 182H, 182J, 182K, 182L, 182M, 182N, 182P, 182Q, 182R, 182S, 182T, R182, T182, TR182, T182T	3A13	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021 Autopilot Servo Installation & Maintenance Manual: 104142-000 Revision D dated 4/28/2023	Autopilot Installation Optional Autotrim Installation Optional	10/21/2022
86	Textron Aviation Inc. (Textron Aviation Inc.) [Cessna Aircraft Company]	185, 185A, 185B, 185C, 185D, 185E, A185E, A185F	3A24	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
87	Textron Aviation Inc. (Textron Aviation Inc.) [Cessna Aircraft Company]	190, 195 (LC-126A, B, C), 195A, 195B	A-790	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	

FEDERAL AVIATION ADMINISTRATION (FAA) APPROVED MODEL LIST (AML)

Original Issue Date March 7, 2018
Revision H December 17, 2025

FOR DYNON AVIONICS STC SA02594SE

INSTALLATION OF THE SKYVIEW HDX INSTRUMENTATION AND AUTOPILOT SYSTEM

ITEM	AIRCRAFT / ROTORCRAFT MAKE	AIRCRAFT / ROTORCRAFT MODEL	ORIGINAL TC NUMBER	CERTIFICATION BASIS FOR ALTERATION	FAA APPROVED DOCUMENTS Number and Revision (or later FAA approved revision)	NOTES AND LIMITATIONS	AML REV DATE
88	Textron Aviation Inc. (Textron Aviation Inc.) [Cessna Aircraft Company]	206, P206, P206A, P206B, P206C, P206D, P206E, TP206A, TP206B, TP206C, TP206D, TP206E, U206, U206A, U206B, U206C, U206D, U206E, U206F, U206G, TU206A, TU206B, TU206C, TU206D, TU206E, TU206F, TU206G, 206H, T206H	A4CE	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
89	Textron Aviation Inc. (Textron Aviation Inc.) [Cessna Aircraft Company]	207, T207	A16CE	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
90	Textron Aviation Inc. (Textron Aviation Inc.) [Cessna Aircraft Company]	210, 210A, 210B, 210C, 210D, 210E, 210F, T210F, 210G, T210G, 210H, T210H, 210J, T210J, 210K, T210K, 210L, T210L, 210M, T210M, 210N, T210N, 210R, T210R, 210-5 (205), 210-5A (205A)	3A21	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
91	Trident (Viking Air, Ltd.)	TR-1	A19EA	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	

**FEDERAL AVIATION ADMINISTRATION (FAA) APPROVED MODEL LIST (AML)
FOR DYNON AVIONICS STC SA02594SE**

Original Issue Date March 7, 2018
Revision H December 17, 2025

INSTALLATION OF THE SKYVIEW HDX INSTRUMENTATION AND AUTOPILOT SYSTEM

ITEM	AIRCRAFT / ROTORCRAFT MAKE	AIRCRAFT / ROTORCRAFT MODEL	ORIGINAL TC NUMBER	CERTIFICATION BASIS FOR ALTERATION	FAA APPROVED DOCUMENTS Number and Revision (or later FAA approved revision)	NOTES AND LIMITATIONS	AML REV DATE
92	True Flight Holdings LLC (True Flight Holdings LLC) [American General]	AA-5, AA-5A, AA-5B, AG-5B	A16EA	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
93	True Flight Holdings LLC (True Flight Holdings LLC) [American General]	AA-1, AA-1A, AA-1B, AA-1C	A11EA	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
94	Univair (Univair Corporation) [Stinson]	108, 108-1, 108-2, 108-3, 108-5	A-767	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
95	WACO (The WACO Aircraft Company)	YMF	ATC 542	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
96	WACO Classic Aircraft Corporation (Great Lakes Aircraft Company)	2T-1A, 2T-1A-1, 2T-1A-2	A18EA	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
97	Zenair (Zenair Ltd.)	CH2000	TA5CH	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	

FEDERAL AVIATION ADMINISTRATION (FAA) APPROVED MODEL LIST (AML)

Original Issue Date March 7, 2018
Revision H December 17, 2025

FOR DYNON AVIONICS STC SA02594SE

INSTALLATION OF THE SKYVIEW HDX INSTRUMENTATION AND AUTOPILOT SYSTEM

ITEM	AIRCRAFT / ROTORCRAFT MAKE	AIRCRAFT / ROTORCRAFT MODEL	ORIGINAL TC NUMBER	CERTIFICATION BASIS FOR ALTERATION	FAA APPROVED DOCUMENTS Number and Revision (or later FAA approved revision)	NOTES AND LIMITATIONS	AML REV DATE
98	ZLIN Aircraft a.s. (ZLIN Aircraft a.s.) [Moravan a.s.]	Z-242L, Z-143L	A76EU	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
99	ZLIN Aircraft a.s. (ZLIN Aircraft a.s.) [Moravan a.s.]	ZLIN 562L	A30EU	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	
100	Piper Aircraft, Inc. (Piper Aircraft, Inc.)	PA-23, PA-23-160, PA-23-235, PA-23-250, Navy UO-1, PA-E23-250	1A10	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	5/28/2024
101	American Navion Society, LTD. (Temco)	D-16, D-16A	2A1	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	5/28/2024
102	Camair	480	2A2	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	5/28/2024
103	Twin Commander Aircraft LLC (Aero Design and Engineering Co.)	560-F, 680, 680E, 680F	2A4	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	5/28/2024

FEDERAL AVIATION ADMINISTRATION (FAA) APPROVED MODEL LIST (AML)

Original Issue Date March 7, 2018
Revision H December 17, 2025

FOR DYNON AVIONICS STC SA02594SE

INSTALLATION OF THE SKYVIEW HDX INSTRUMENTATION AND AUTOPILOT SYSTEM

ITEM	AIRCRAFT / ROTORCRAFT MAKE	AIRCRAFT / ROTORCRAFT MODEL	ORIGINAL TC NUMBER	CERTIFICATION BASIS FOR ALTERATION	FAA APPROVED DOCUMENTS Number and Revision (or later FAA approved revision)	NOTES AND LIMITATIONS	AML REV DATE
104	Textron Aviation Inc. (Textron Aviation Inc.) [Cessna Aircraft Company]	310, 310A, 310B, 310C, 310E, 310F, 310G, 310H, E310H, 310I, 310J, 310J-1, E310J, 310K, 310L, 310N, 310P, T310P, 310Q, 310R, T310R, USAF U-3A USAF E-3B	3A10	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	5/28/2024
105	Textron Aviation (Textron Aviation Inc.) [Beechcraft]	95, B95, B95A, D95A, E95	3A16	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	5/28/2024
106	Textron Aviation (Textron Aviation Inc.) [Beechcraft]	95-55, 95-A55, 95-B55, 95-B55A, 95-B55B (T-42) 95-C55, 95-C55A, D55, D55A, E55 E55A, 56TC, A56TC	3A16	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	5/28/2024
107	Textron Aviation (Textron Aviation Inc.) [Beechcraft]	65, 65-80, A65	3A20	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	5/28/2024
108	Textron Aviation Inc. (Textron Aviation Inc.) [Cessna Aircraft Company]	320, 320-1 320A, 320B, 320C, 320D, 320E, 320F, 335	3A25	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	5/28/2024

**FEDERAL AVIATION ADMINISTRATION (FAA) APPROVED MODEL LIST (AML)
FOR DYNON AVIONICS STC SA02594SE**

Original Issue Date March 7, 2018
Revision H December 17, 2025

INSTALLATION OF THE SKYVIEW HDX INSTRUMENTATION AND AUTOPILOT SYSTEM

ITEM	AIRCRAFT / ROTORCRAFT MAKE	AIRCRAFT / ROTORCRAFT MODEL	ORIGINAL TC NUMBER	CERTIFICATION BASIS FOR ALTERATION	FAA APPROVED DOCUMENTS Number and Revision (or later FAA approved revision)	NOTES AND LIMITATIONS	AML REV DATE
109	Bay Aviation	Super V	3A29	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	5/28/2024
110	Textron Aviation (Textron Aviation Inc.) [Beechcraft]	50 (L-23A), B50 (L-23B), C50, D50 (L-23-E), D50A, D50B, D50C, D50E, D50E-5990, E50 (L-23D), E50 (RL-23D), F50, G50, H50, J50	5A4	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved Operation of JATO rocket engines when STC SA02594SE is installed is prohibited.	5/28/2024
111	Grumman	G-21, G-21A	654	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	5/28/2024
112	Twin Commander Aircraft LLC (Aero Design and Engineering Co.)	500, 500A, 500B, 500U, 520, 560, 560A, 560E, 500S	6A1	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	5/28/2024
113	GippsAero	GA8, GA8-TC320	A0011LA	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	5/28/2024
114	Textron Aviation Inc. (Textron Aviation Inc.) [Cessna Aircraft Company]	207A, T207A	A16CE	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	5/28/2024

FEDERAL AVIATION ADMINISTRATION (FAA) APPROVED MODEL LIST (AML)

Original Issue Date March 7, 2018
Revision H December 17, 2025

FOR DYNON AVIONICS STC SA02594SE

INSTALLATION OF THE SKYVIEW HDX INSTRUMENTATION AND AUTOPILOT SYSTEM

ITEM	AIRCRAFT / ROTORCRAFT MAKE	AIRCRAFT / ROTORCRAFT MODEL	ORIGINAL TC NUMBER	CERTIFICATION BASIS FOR ALTERATION	FAA APPROVED DOCUMENTS Number and Revision (or later FAA approved revision)	NOTES AND LIMITATIONS	AML REV DATE
115	Britten-Norman Aerospace Ltd. [Pilatus Britten-Norman Limtd.]	BN-2, BN-2A, BN-2A-6, BN-2A-8, BN-2A-2, BN-2A-9, BN-2A-3, BN-2A-20, BN-2A-21, BN-2A-27, BN-2B-20, BN-2B-21, BN-2B-26, BN-2B-27	A17EU	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	5/28/2024
116	Cougar Aircraft Corporation [Grumman American]	GA-7	A17SO	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	5/28/2024
117	Air Tractor	AT-401, AT-401A, AT-401B, AT-501	A17SW	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	5/28/2024
118	Aerostar [Aerostar Aircraft Corporation]	PA-60-600 PA-60-601	A17WE	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	5/28/2024
119	Piper Aircraft, Inc. (Piper Aircraft, Inc.)	PA-44-180, PA-44-180T	A19SO	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	5/28/2024
120	Piper Aircraft, Inc. (Piper Aircraft, Inc.)	PA-30, PA-39	A1EA	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	5/28/2024

**FEDERAL AVIATION ADMINISTRATION (FAA) APPROVED MODEL LIST (AML)
FOR DYNON AVIONICS STC SA02594SE**

Original Issue Date March 7, 2018
Revision H December 17, 2025

INSTALLATION OF THE SKYVIEW HDX INSTRUMENTATION AND AUTOPILOT SYSTEM

ITEM	AIRCRAFT / ROTORCRAFT MAKE	AIRCRAFT / ROTORCRAFT MODEL	ORIGINAL TC NUMBER	CERTIFICATION BASIS FOR ALTERATION	FAA APPROVED DOCUMENTS Number and Revision (or later FAA approved revision)	NOTES AND LIMITATIONS	AML REV DATE
121	Piper Aircraft, Inc. (Piper Aircraft, Inc.)	PA-31, PA-31-300, PA-31-325, PA-31-350,	A20SO	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved Installation in aircraft with 11 total seats not approved.	5/28/2024
122	Textron Aviation Inc. (Textron Aviation Inc.) [Cessna Aircraft Company]	404	A25CE	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved Installation in aircraft with 11 total seats not approved.	5/28/2024
123	Piper Aircraft, Inc. (Piper Aircraft, Inc.)	PA-46R-350T	A25SO	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	5/28/2024
124	Textron Aviation (Textron Aviation Inc.) [Beechcraft]	76	A29CE	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	5/28/2024
125	Textron Aviation Inc. (Textron Aviation Inc.) [Cessna Aircraft Company]	336	A2CE	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	5/28/2024
126	Textron Aviation Inc. (Textron Aviation Inc.) [Cessna Aircraft Company]	T303	A34CE	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	5/28/2024

FEDERAL AVIATION ADMINISTRATION (FAA) APPROVED MODEL LIST (AML)

Original Issue Date March 7, 2018
Revision H December 17, 2025

FOR DYNON AVIONICS STC SA02594SE

INSTALLATION OF THE SKYVIEW HDX INSTRUMENTATION AND AUTOPILOT SYSTEM

ITEM	AIRCRAFT / ROTORCRAFT MAKE	AIRCRAFT / ROTORCRAFT MODEL	ORIGINAL TC NUMBER	CERTIFICATION BASIS FOR ALTERATION	FAA APPROVED DOCUMENTS Number and Revision (or later FAA approved revision)	NOTES AND LIMITATIONS	AML REV DATE
127	Mitchell [KWAD Company]	Super-V	A5IN	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	5/28/2024
128	Textron Aviation Inc. (Textron Aviation Inc.) [Cessna Aircraft Company]	337, 337A (USAF 02B), 337B M337B (USAF 02A), T337B, 337C, T337C, 337D, T337D, 337E, T337E, 337F, T337F, 337G, 337H, T337H, T337H-SP	A6CE	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved Engine Monitor System Installation Not Approved	5/28/2024
129	Grumman	G-44 (Army OA-14) (Navy J4F-2), G-44A, SCAN Type 30	A-734	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	5/28/2024
130	Textron Aviation Inc. (Textron Aviation Inc.) [Cessna Aircraft Company]	401, 401A, 401B, 402, 402A 402B, 402C, 411, 411A	A7CE	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	5/28/2024
131	De Havilland [Viking Air Limited]	DHC-2 Mk. I DHC-2 Mk. II	A-806	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	5/28/2024

**FEDERAL AVIATION ADMINISTRATION (FAA) APPROVED MODEL LIST (AML)
FOR DYNON AVIONICS STC SA02594SE**

Original Issue Date March 7, 2018
Revision H December 17, 2025

INSTALLATION OF THE SKYVIEW HDX INSTRUMENTATION AND AUTOPILOT SYSTEM

ITEM	AIRCRAFT / ROTORCRAFT MAKE	AIRCRAFT / ROTORCRAFT MODEL	ORIGINAL TC NUMBER	CERTIFICATION BASIS FOR ALTERATION	FAA APPROVED DOCUMENTS Number and Revision (or later FAA approved revision)	NOTES AND LIMITATIONS	AML REV DATE
132	Air Tractor	AT-250, AT-300, AT-301	A9SW	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	5/28/2024
133	Partenavia [Vulcanair S.p.A.]	P.68, P.68B, P.68C, P.68C-TC, P.68 "OBSERVER" P.68TC "OBSERVER", P.68 "OBSERVER 2", P.68R	A31EU	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	5/28/2024
134	Univair [Engineering and Research Corp.]	415-C, 415-CD	A-718	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	5/28/2024
135	Univair [Engineering and Research Corp.]	415-D, E, G, F-1, F1-A, A-2, A-2A, M10	A-787	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	5/28/2024
136	Piaggio	P.136	A-813	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision Q dated 11/5/2021, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021	Autopilot Installation Not Approved	5/28/2024

**FEDERAL AVIATION ADMINISTRATION (FAA) APPROVED MODEL LIST (AML)
FOR DYNON AVIONICS STC SA02594SE**

Original Issue Date March 7, 2018
Revision H December 17, 2025

INSTALLATION OF THE SKYVIEW HDX INSTRUMENTATION AND AUTOPILOT SYSTEM

ITEM	AIRCRAFT / ROTORCRAFT MAKE	AIRCRAFT / ROTORCRAFT MODEL	ORIGINAL TC NUMBER	CERTIFICATION BASIS FOR ALTERATION	FAA APPROVED DOCUMENTS Number and Revision (or later FAA approved revision)	NOTES AND LIMITATIONS	AML REV DATE
137	Mooney (Mooney International Corporation) [Mooney Aviation Company, Inc.; Mooney Airplane Co.; Mooney Aircraft Corporation; Aerostar Aircraft Corp]	M20J, M20K	2A3	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision V dated 8/9/2024, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision M dated 5/2/2024 Autopilot Servo Installation & Maintenance Manual: 104368-000 Revision A dated 4/4/2024	Autopilot Installation Optional Autotrim Installation Optional	9/26/2024
138	Textron Aviation (Textron Aviation Inc.) [Beechcraft]	P35	3A15	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision V dated 8/9/2024, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision N dated 10/11/2024 Autopilot Servo Installation & Maintenance Manual: 104938-000 Revision B dated 8/14/2024	Autopilot Installation Optional Autotrim Installation Optional	1/3/25
139	Mooney (Mooney International Corporation) [Mooney Aviation Company, Inc.; Mooney Airplane Co.; Mooney Aircraft Corporation; Aerostar Aircraft Corp]	M20C, M20D, M20E, M20F	2A3	Unchanged from TCDS except electrical systems requirements at Amdt 63 and HIRF and lightning at Amdt 64.	Installation Manual: 103261-000 Revision K dated 11/23/2021 Airplane Flight Manual Supplements: 103272-000 Revision W dated 12/17/2025, and 104004-000 Revision A dated 5/24/2023 Instructions for Continued Airworthiness: 103221-000 Revision I dated 10/21/2021 Autopilot Servo Installation & Maintenance Manual: 104374-000 Revision C dated 10/23/2025	Autopilot Installation Optional Autotrim Installation Optional	12/17/2025